Certificate of Location of Government Corner

ID#: 550105 **Description:** SEC COR 1 2 11 12 55 **Date Set:** 4/24/1974 **County:** Olmsted

Section: 01 **Township:** 105N **Range:** 15W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 13' east of centerline of CSAH 15
Ref pipe SW 71.12'
This corner is located by GPS measurement

Corner History:

5-30-1854 Gov't Notes: M. Karrick, North between sections 11 and 12. 80.00 chs. Set post for corner. Dug trench. Burr Oak 13 in. N22W 420 lks.

4-1876 Thomas Hunter (No.286 P.291), County Surveyor, states no positive corner found, but the old fence post was claimed to have been set by the side of the original corner. Measured east 80.13 chs. To an undesputed stake in a mound.

4-24-1974 County Surveyor reset this corner by lost methods, set it midway between the section corners east and west (5247.20') and set it 1/3 distance from the fence lines at the 1/4 Cor. 1-2 to the section corner at 11-12-13-14 where used the Co.H.D. corner. Set a C.I.M. over a 5/8"x24" rod.

6-27-1996 County Surveyor found CIM on East road shoulder of CR #15 14 1/2' East of centerline. Set REF pipe SW of cor. on West ditch slope of CR #15. Top angle at REF pipe. Angle RT P.K. in PP# 43109 (2nd pole North of cor. on East side CR #15) to sec. cor. 1-2-11-12 22° 40' 19". To sec cor HOR 71.12. Note: REF pipe is 20' West of centerline left CIM in rock shoulder.

11-1-2002 County Surveyor found CIM down 0.5' in good condition.