Certificate of Location of Government Corner

ID#: 550205 **Description:** SEC COR 2 3 10 11 55 **Date Set:** 7/22/1971 **County:** Olmsted

Section: 02 **Township:** 105N **Range:** 15W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls in centerline of CR 126 west and 1 1/2' east of centerline of CR 126 north
Top center N end 30" CMP NE 29.0'
Rivit in S end 30" CMP SE 31.2'
Center of bottom of massive power control switch mast lever SE 54.15'
This corner is located by GPS measurement

Corner History:

1857 John Fellows (Pg.42 No.64) show sec. corner 1/16 West 19.77 chs. M & L to 1/4 post (see survey for interior breakdown of sec. 10)

6-1898 W. Fraser (P520 No.486 S.11) H. Skjerner found stone set in center of roads, tested by S.W. B.T. still standing and found corner correct. Meas South 39.91 1/2 (2634.39 to stone 3 x 12 x 20) set M & L.

1939 County Highway Department found Limestone with stake on North side (B99 P.99) Sp. F.P. NE 77.0. Sp F.P. SE 82.7 Cross N leadwall culv NE 21.95, S. headwall SE 20.4 Meas West 5272.7.

12-1949 J. Kerr (B.44 P.42) found stone set 1" pipe riser, Sp. PP SE 47.0, Sp Fe post NE 61.3.

7-22-1971 County Surveyor dug by hand, found 60d down 3", hub down 8", 1" pipe down 18". Top recorded limestone down 4' stake N side. Reset 1" pipe in stake hole, bending to center over limestone with CIM over pipe and stone. Meas South to stone found (reset by J. Kerr 1949) 2633.15 then 2634.3 to 10-11-14-15 (R 2634.4 M & L) 1/4 corner found .14 West direct line .57 N of midway. RP's 2-3-10-11 corner in center tee road intersection. 29.0 NE to top center N edge of N end 30" field drive culv. 31.2 SE to rivit top center S end 30" field drive culv. 54.15 SE to center of bottom of massive power control switch mast lever. 217.7 WSW to hard nail in knot N side PP 44294.

11-1-2002 County Surveyor found CIM down 0.7' in good condition.