Certificate of Location of Government Corner

ID#: 550506 **Description:** 1/4 SEC COR 5 6 55 **Date Set:** 6/16/2005 **County:** Olmsted

Section: 05 **Township:** 105N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in centerline of N-S twp road, in E-W PP line and in centerline with field entrance west
County highway disk in PP #24725 E 32.68'
This corner is located by GPS reference stations "Stensrud & Schmoll A"

Corner History:

5-1854 Michael Karrick 39.85 S. set quarter section post. Black Oak 10 S 50 E 635. Dug Trench. 50.80 stream 35 lks wide runs East.

8-9-1984 County Surveyor dug from the traverse nail (set in the centerline N-S road and in line with fences E & W) for 4' North, 6' South, 10' West and 10' East. Found the possible remains of a stake in the area 9 1/2' East of the t.n. (two wood pieces about 4" long and 2" diameter) but could not find a hole where it could have stood. Someone had dug in the center of the road from the line of the fence, South for 7' by appx 3' wide. We were digging 3 1/2' ± deep here. The oldest road was covered with sand and there was 6" to 1' of dirt beneath it. The diggings found was beneath the road. We also dug across the road from 13' to 23' South of the t.n. to cover prorated location as per Will Fraser's survey but did not find anything further. Although W. Fraser does not mention the fence, it is an old property line and was doubters there when he surveyed, therefore we will hold the N-S loc. of t.n. when corner set.

8-10-1984 1/16 North County Suveyor dug from a point on line from the CIM at No 5-6 to the t.n. at 1/4 5-6 (nail in centerline N-S road and in line fences E and W) and in line with old fence bulkhead running East for 4' North, 6' South, 5' West, and 3' East by 5 1/2 deep to clay. Black dirt down 4 1/2'. Very good conditions and bulkhead fits prorated Gov't measure to fence at 1/4 cor. 5-6.

8-13-1984 County Surveyor dug 5' more off E edge of hole. Black dirt to 6 1/2' here but no corner.

6-16-2005 County Surveyor found 1/2" rerod down 0.3' in good condition set by county highway department 0.06' north and 0.04' east of corner position. Removed rerod and set 5' telspar pipe w/Cast Iron Cap down 0.4' from GPS and traverse data coordinates.