Certificate of Location of Government Corner

ID#: 550706 **Description:** W 1/4 SEC COR 7 55 **Date Set:** 11/13/2002 **County:** Olmsted

Section: 07 **Township:** 105N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in line with fences north, south and east
Steel fence post 1' west
Post w/sign 1' east
This corner is located by GPS measurement

Corner History:

10-1854 John Ball; 40.0 set post for quarter section corner. RPs- 10" black oak N 2 1/2° east 277 links, 10" black oak S36W 238 links. 40.0 leave oak opening and enter dry prairie bottom, bears SW. 54.90 brook 10 links wide runs NE.

11-13-2002 Olmsted County Surveyor dug at fence corner to fences N-S-E. Checked for Gov't Witness trees and found none. Corner post ran 5' deep into water table with about 1' of water in hole when we pulled post stub. Put post stub back in hole. Set 6' telspar pipe w/cast iron cap at nail position from previous survey which falls 1' SE of post stub corner post. Set post w/sign 1' East.

2-23-2010 Olmsted county survey crew found cast iron cap on telspar pipe up 0.5' in good condition