Certificate of Location of Government Corner

ID#: 551005 **Description:** SEC COR 9 10 15 16 55 **Date Set:** 4/21/2009 **County:** Olmsted

Section: 10 **Township:** 105N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in centerline of N-S twp road and 1' south of centerline of E-W twp road
Center 16" Burr Oak NE 85.1'
County Survey Disk in twin Burr Oak SE 88.56'
Center 30" Burr Oak SW 76.6'
County highway disk in PP SW 44.16'
This corner is located by GPS measurement

Corner History:

11-1857 John Fellows (Pg.42 No.64) shows sec. corner 1/16 East 19.89 chs. M & L to 1/4 post. Meas North 39.80 chs. to 1/4 post. (see survey for interior breakdown of sec. 10)

6-1875 T. Hunter (P.280 No.277) found stone in center road claimed set by Freeman, surveyor when B trees were in place.

7-25-1966 J. Kerr found limestone as recorded. Set CIM over original stone with 1/2"x2' rods on 2 sides of stone.

9-12-1984 County Surveyor found CIM in good condition.

9-30-1988 County Surveyor found CIM in good condition down 1' in gravel road. Took new RP 59.90' SE to CSD in NE side of corner post.

4-20-2009 County Surveyor found CIM down 1.2' in good condition.

4-21-2009 County Surveyor removed CIM found 3"x4"x12" stone down 3.1' in good condition, removed. Set 4' telspar pipe w/Cast Iron Cap down 0.5' from ties taken from CIM.