Certificate of Location of Government Corner

ID#: 551405 **Description:** SEC COR 14 15 22 23 55 **Date Set:** 9/11/2006 **County:** Olmsted

Section: 14 **Township:** 105N **Range:** 15W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The monument is down 0.4'
The corner falls 11 1/2' west of centerline of N-S twp road and 56 1/2' south of centerline of TH 30
County highway disk in SW side PP #6814 SE 51.07'
Minnesota Highway Disk in S side PP #6804 WSW 66.3' (blocked by TCM box)
NE corner house foundation SW 90.6'
60d spike in NW side 12" Pine SW 42.21'
This corner is located by GPS measurement

Corner History:

1854 Gov't Notes North between 22 and 23. 80.00 chs. Set section corner post. Erected mound with trench, pits, charred stake, and osage orange seeds at each angle.

4-1878 Thomas Hunter (P.334 No.328), County Surveyor, found boulder stone in center of road and set a larger stone 4"x8"x20".

10-18-1973 County Surveyor found recorded size boulder 5"x8"x20" 5' deep. Set a 1 1/4"x20" drill rod over stone with C.I.M. over all flush with road surface. Corner fell 4.53' south and 6.72' west of rod in place. (Set by J. Kerr).

9-27-1988 County Surveyor found CIM in good condition.

6-24-1993 County Surveyor found CIM in good shape 10" down in shoulder of twp rd running South of T.H.30 centerline twp rd East 11 1/2'. Centerline T.H.30 North 56 1/2'.

9-6-2006 County Surveyor found CIM down 1.9' leaning west, removed. Found 1 1/4' rod down 3.5' in good condition, took local ties. Checked tie to PP SE 51.05'.

9-11-2006 County Surveyor set 1" square pipe w/cap at surface from local ties taken from rod. Disc in SW side of PP #6814 SE 51.07' and 60d spike in NW side of 12" Pine SW 42.21'. Tie to the WSW blocked by TCM box, did not check tie to house foundation.

4-26-2013 County survey crew found 1" square pipe with cap at surface in good condition. Lowered pipe and cap 0.4' in preparation for 2013 road overlay.