Certificate of Location of Government Corner

ID#: 551705 **Description:** SEC COR 17 18 19 20 55 **Date Set:** 7/11/2003 **County:** Olmsted

Section: 17 **Township:** 105N **Range:** 15W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The monument is down 0.5'
The corner falls 9' north of centerline of TH 30, in centerline of twp road north and in line with fence south

Corner History:

5-1854 Michael Karrick 80.00 set post for corner to sections 17,18,19 and 20 Erected mound with trench, pits, charred stake and osage orange seeds at each angle.

6-1895 W. Fraser (P.579 No.529) found stake in center road, 50 chs. W and 50 chs. S of corner post of fence standing in row of willows running East and North on East and North side of road. Drove new stake with stones piled around it as section corner. Meas North 39.95 to 8 x 10 x 30 boulder set M & L. Meas East 40.12 to stake set with stone by side. Then 39.88 (2632.08 to school corner 16-17-20-21.

MHD No. 30 notes: Took centerline fence South as station 5274.5 which makes 2638.4 West to S 1/4 18 record 2642.3. Centerline highway 30 lies 5.2 South of section line as state assumed it from centerline old road.

10-16-1973 County Surveyor projected line and measure 2635.5 from North over CIM in place as recorded. Drove RR spike in new 30 hwy blacktop with punch center. 9' North approx center road in exact line of fence S, road North.

7-11-2003 County Surveyor found RR spike down 0.3'. Removed RR spike and set 1" square pipe w/cap down 0.1' from local ties.

9-6-2006 County Surveyor found 1" square pipe w/cap in good condition near surface.

4-25-2013 County survey crew found 1" square pipe with cap at surface in good condition. Lowered pipe and cap 0.5' in preparation for 2013 road overlay.