Certificate of Location of Government Corner

ID#: 551904 **Description:** 1/4 SEC COR 19 30 55 **Date Set:** 8/20/2009 **County:** Olmsted

Section: 19 **Township:** 105N **Range:** 15W **Monument Description:** Cast Iron Cap on Telspar Pipe

Reference Ties:

The monument is down 0.3'
The corner falls 2' west of centerline of CR 149 and 2' north of centerline of E-W twp road
This corner is located by GPS measurement

Corner History:

5-1854 Michael Karrick 39.70 set quarter section post in mound with trench, pits, charred stake and Osage Orange seeds NE and SW.

6-1895 W. Fraser (P.582 No.531) corner gone. A muddy wet corner. Located corner on line and prop meas. W 39.73 1/2 (2622.5) and E 40.03 1/2 (2642.3). 1/16 East set stake M & L 20.01 3/4 with 1/64 stake East of above 1/16 M & L 10.00 7/8.

8-10-1965 County Surveyor replaced from notes of former surveys. Set CIM over 1/2"x18" rod on proportional measurement and line.

5-1-1980 County Highway Department (Book 477 pg.8) found CIM in good condition. Took ties.

9-18-2006 County Surveyor found CIM down 2' in good condition.

8-20-2009 County survey crew found CIM down 1.7' in good condition. Removed CIM and found 1/2" rod directly below. Removed 1/2" rod and replaced it with a 5' telspar pipe with cast iron cap down 0.5'

4-24-2012 County survey crew found cast iron cap in good condition.