Certificate of Location of Government Corner

ID#: 552004 **Description:** 1/4 SEC COR 20 29 55 **Date Set:** 9/24/1992 **County:** Olmsted

Section: 20 **Township:** 105N **Range:** 15W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 5' north of centerline of E-W twp road and 2' west of centerline of twp road north

Corner History:

5-1854 Michael Karrick 40.00 set quarter section post in mound with trench, pits, charred stake and Osage Orange seed NE and SW.

9-1876 T. Hunter (P.304 No.299) found mound and 2 pits with bark lined hole in center mound, set new stake with 2 x 6 x 18 stone on South side of stake. Meas West 40.00 used in setting NW 29.

5-1896 T. Hunter (P.598 No.543) found stone set P.304. 16E set oak stake in center road M & L 19.92 1/2 (1315.05) bearing of 1/4 line S N 1/2° E, bearing section line E N 88 1/2 W. Used to set center sec. 29 no meas from center North but meas and corners E-W-S from center (could not find 1/16 S).

7-27-1971 County Surveyor, meas from nail in center CR 3 blacktop West found 1/16 fence South where Hunter set stake at 1319.8 (R 1315.05) con't line West set nail in center roads E-W-N at 63.43 NW to center metal TP 2632.0 RP 48.0 NE to center PP #6172.

7-29-1971 County Surveyor dug enormous hole 3/4 width of road covering E-W found boulders but no limestones.

7-30-1971 County Surveyor, meas East from CIM at 19-20-29-30 2640.0' nail set as 00 came about 2644.1. Ran line from corner post at 1/4 29-32 over corner post at 1/4 29-32 at center 29 on 16' offset West over corn fields. This line at center came 21.4 offset West or should be 26.8 West at 1/4 20-29 line fell 25.9 West of 2640 from CIM West. Line fell 30.0 West of 2632 nail from East.

8-13-1971 County Surveyor dug again North-South and West of former diggings found 1/4 corner 20-29

9-21-1992 County Surveyor, 1/16th East dug with backhoe in center of gravel road found T. Hunter's oak stake in fair but rotted condition. The top was down 2 1/2' below road surface, there was 19" of stake remaining the corner falls ± 1 North of centerline E-W rd and 1 1/2' West of fence line South. Set 3/8" rod in stake hole, showed the stake to the Lee brothers they were impressed set 60d spike at surface.

9-24-1992 County Surveyor set CIM over 1/2" iron by doubling line and measure over 1/16th E stake fd 9/21. RP's The corner falls 5' North of centerline E-W twp road and 4' West of centerline twp rod North. CSD in PP #47071 NE 47.69 top center TP box NW 56.3.

9-8-2006 County Surveyor found CIM in good condition down 0.5'. Ties there but did not check.