Certificate of Location of Government Corner

ID#: 552206 **Description:** 1/4 SEC COR 21 22 55 **Date Set:** 4/23/2009 **County:** Olmsted

Section: 22 **Township:** 105N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in centerline of N-S twp road and 11' south of centerline of field ent west

Corner History:

5-1854 Gov't Notes Michael Karrick, Deputy Surveyor North between Section 21 & 22 40.00 chs. Set 1/4 section post in mound with trench pits, charred stake and osage orange seeds NE & SW.

8-29-1986 County Surveyor dug with backhoe 12' wide E-W and 13' long N-S 4' deep to clay. The old road was down 2 1/2'. Found a limestone standing but shattered into many pieces and dug in with mark in clay top down 3'. Removed stone pieces and found nothing further.

9-2-1986 County Surveyor drove 4' long telespar pipe w/Cast Iron Cap at location of shattered stone.

8-8-1995 County Surveyor blade operator had reported (6-30-1995) finding cap when he was blading road. We found pipe bent on top and badly torn. We checked trav. Tie and ties and found pipe to be in good position. We pulled pipe and set 6' telspar w/cap down 0.8'.

4-23-2009 County Surveyor found telspar pipe at surface torn and bent. Cut off torn part of pipe, lowered and set CIC on pipe down 0.6'.