Certificate of Location of Government Corner

ID#: 552406 **Description:** 1/4 SEC COR 23 24 55 **Date Set:** 6/29/2007 **County:** Olmsted

Section: 24 **Township:** 105N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 2' east of centerline of CR 115 and in line with fence west
County Survey Disk in NE side PP NNW 89.79'
NW corner of garage foundation ESE 65.20'
Corner of house foundation SE 152.97' (blocked by shrub)
Punched cross in N end 15" CMP SE 42.03'
This corner is located by GPS measurement

Corner History:

5-1854 Michael Karrick 40.00 set quarter section post in mound with trench, pits, charred stake and Osage Orange seeds NE and SW.

1878 T. Hunter (BK. A pg.334) found the remains of the old stake in a mound and he set a 6" by 10" by 20" stone in it's place.

7-21-1971 County Surveyor found recorded boulder. Lowered stone, set 3/4"x14 1/2" reinforced rod below the stone with CIM on top.

10-25-1973 County Surveyor, electronic meas South (2638.66). Electronic meas North (2643.93) to RR spike as corner. (2643.93) As to how 1/4 23-24 lies as to line very close to being on direct line easy to check direct.

6-28-2007 County Surveyor found 1/2" pipe w/cap RLS #15809 down 0.7' in good condition. Removed 1/2" pipe and found CIM down 1.5' in good condition.

6-29-2007 County Surveyor found CIM down 1.5' in good condition, took local ties and removed. Found stone down 3 1/2' in good condition, did not check ties. Set 3' telspar w/CIC down 0.45' from ties taken from CIM. Updated ties.