Certificate of Location of Government Corner

ID#: 552504 **Description:** 1/4 SEC COR 25 36 55 **Date Set:** 10/31/1984 **County:** Olmsted

Section: 25 **Township:** 105N **Range:** 15W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 9 1/2' south of centerline of E-W twp road and in line with fences north and south
This corner is located by GPS measurement

Corner History:

5-1854 Michael Karrick 40.00 set quarter section post. Burr Oak 8 S 30 E 414. Dug trench.

4-1906 Chas Armstrong (P.106B) has "stone" written on plat as N 1/4 36, no meas, no disc. Used to set center 36 which comes in river.

11-8-1971 County Surveyor projected aerial from 20' offset West of S 1/4 36 CIM over 20' offset West at cross on 1/16 stone. 1329' North of S 1/4 36 (R 1326.6) could easily see direct to 1/4 25-36 in road. air clear temp 36°. Area has no N-S fences within 80 rods grade filled 3'± but no abrupt wash area. Good chance stone stone could be in place. Set 40d on North and South edges of road in grass font.

10-25-1973 County Surveyor found 20' offset nails both torn out but not moved very far. Replaced exactly from RP's. Meas from CIM at E 25-36 West, found 1/16 property fence South at 1316±. 20' East of offset nails. Corner would come at 2635 did not meas West to CIM at 25-26-35-36. Dug entire road nearly from 3' West of 20' line to 5' East of 20' line to clay or water, much black dirt. Found a few small boulders in sub grade near clay but no wood or corner stones. 20' offset line could be checked with farm property corner as 1/16 South but N-S line may be very close. Set transit on crest some 500' West and road line very near center E and West so corner could be put on line and intersect offset line from South or see if midway would come close. Armstrong corner lost and gone if ever set.

10-26-1984 County Surveyor found spikes on North and South edge of road set in 1971 on a 20' offset West of line from the S 1/4 cor. 36 over Armstrong's stone at the 1/16 North (actually nails replaced in 1973) see 1984 remon. BK for digging sketch. Dug across road 20' East of nails. Enlarged on 1973 dig. Found a stone boulder 4" x 5 1/2" x 20" that had been broken in half, one piece set vertical and the other laid on tip. Stone down 3.0' Removed stone. The way they were placed showes that they had not been broken off by road construction. There was still black dirt beneath the stones, but at clay line 4.7 deep found 2" drain mark directly beneath vertical stone and extending into clay 4 or 5 inches. It appeared to be stake mark although now filled with black dirt fairly hard packed. Stake possibly pulled out when stone set. Stone 9 1/2' So of centerline E-W road and is 24.6 E off offset line. Found a post stub on the North side of road 8 1/2' N of centerline and 22.1 E of offset line. There was another longer post on the North side of this post that had been cut off by road construction. Believe these the corner posts to previous fence North and the road probably straightened out.

10-31-1984 County Surveyor set CIM over a 5/8" re-rod at the location of stake mark and stone (removed) found corner 9 1/2 South centerline E-W road and 161' East of center of field drive on North side of road.

6-28-2007 County Surveyor found CIM down 0.7' in good condition.