Certificate of Location of Government Corner

ID#: 553109 **Description:** SEC CEN 31 55 **Date Set:** 8/16/1971 **County:** Olmsted

Section: 31 **Township:** 105N **Range:** 15W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.
1/2" rod

Reference Ties:

The corner falls in centerline of CR 149, 1' north of centerline of CR 108 east and 1' north of centerline of twp road west
County highway disk in PP NE 50.60'
County highway disk in top CP SE 68.90'
This corner is located by GPS reference stations "Hot & Quiet"

Corner History:

6-11-1875 T. Hunter (P.284 No.281) set stake at inters lines. 1/16 West set stake on line and porp meas 20.15 then 19.95 computed G meas 39.80 actual 40.10 thus above meas. 16 East set marked stake M&L 19.95 (1816.7) S 88° 36' W. 16 North set marked stake M&L 20.01 1/4 (1320.82) N 3/4° W. 16 South set marked stake M&L 19.93 (1315.38) 16 center NE 1/4 marked stake M&L 19.92 on E-W 1/16 line. 16 center NW 1/4 marked stake inters lines. Stakes set East of 1/16 South 12.97 1/2 then 12.97 1/2 then 13.97 1/2 16 West.

6-9-1898 W. Fraser (P.635 No.573) found Hunters stake in center road proved by inters lines replaced stake with stone 2 x 8 x 20. 16 North set stake and stone M&L 20.00 1/4 couldn't find stake N 20' E. 16 South set stake and stone M&L 19.92 couldn't find stake. Set stakes East above 1/16 12.96 then 12.96 then 13.96 also set 1/16 stake East above 1/16 M&L 19.94. 16 East set stone and stake M&L 19.92 1/2 found Hunters stake ok N 89° 15' W. 16 West set new stake and stone line and 20.13 then 19.93 found Hunters stake.

8-9-1971 County Surveyor set nail in center inters roads on transit random line. RP's 36.4 SE to SE corner conc headwall of N-S culvert 33.2 NE to NE corner conc headwall of N-S culvert. Nail set 2626.2 from random nail set at 1/4 31-32 1316.27 from random nail set at 1/16 East.

8-16-1971 County Surveyor found large wood post and limestone 2 x 8 x 10 with decided road surface near top of stone indicating that cap of stone could have been broken off by road action. Found described corner .9 South and .2 East of nail set. Meas East to 1/16 stone found 1315.32 (R2630.4) Set iron rod as temp corner, riser over stone found no further RP's.

5-1-1980 county highway department (Book 477, Pg 5) found 1/2" rerod in good condition. Took ties.

2-28-1990 V. Fangman used computed center at intersecting quarter lines.

7-3-2007 GGG, Inc. used 1/2" rod as center of section 31 for survey in SW 1/4.

5-4-2009 County Surveyor did not find 1/2" rod.