Certificate of Location of Government Corner

ID#: 553205 **Description:** S SEC COR 32 33 55 **Date Set:** 10/9/2003 **County:** Olmsted

Section: 32 **Township:** 105N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 1 1/2' SE of CP
30d spike in 24" Oak NNW 31.83'
Post with sign 2' south
This corner is located by GPS measurement

Corner History:

9-1853 Gov't Notes 53.70 creek 20 lks wide runs SE. 80.00 set post for corner to sec 31 & 32, built mound with trench per instructions. Drove charred stake in center and planted Apple tree seed on NW corner.

6-1875 T. Hunter (P.282 No.279) corner standing in mound used to set 1/4 31-32 M&L no meas given.

6-14-1875 T. Hunter unrecorded SE 31 given as 5.51 East of N 1/4 5.

6-11-1875 T. Hunter (P.284 No.281) found original stake standing in remains of mound at corner of field. 1/16 North set temp stake M&L 19.96 N 1° W. West set stakes at 13.98 1/3 then 12.98 1/3 then 12.98 1/3 to S 1/4 31. West of 1/16 North set stakes West at 13.97 1/2 then 12.97 1/4 then 12.97 1/4 to 1/16 corner.

6-1898 W. Fraser (P.633 No.572) found post in mound averred by Mr. Holland that he set post in place of stake. 5.51 East of N 1/4 5. 6" Burr Oak N 28 1/4 W 22 lks.

6-1923 J. Kerr (P.392B book 8 page 11) Hennesy uncompleted survey. Found stake replaced same.

1935 county highway department set stake M&L (book 79).

1940 county highway department (B.109) found 3/4" bolt 6" South corner post. 362.8 East of N 1/4 5. 363.66 is record for 5.51 chs.

2-1990 Vince Fangman found bolt with 1" sq head down 1.0'.

10-9-2003 County Surveyor found 1"x3' square head bolt down 0.7' in good condition. Took local ties and removed bolt. Set 6' telspar pipe w/cast iron cap up 0.3'.

3-4-2010 County Surveyor found cast iron cap on telspar pipe at surface in good condition.