Certificate of Location of Government Corner

ID#: 553304 **Description:** S 1/4 SEC COR 33 55 **Date Set:** 7/18/2002 **County:** Olmsted

Section: 33 **Township:** 105N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is up 0.2'
The corner falls 1' west of fence north and 3 1/2' north of E-W fence
Post w/sign 1 1/2' south
This corner is located by GPS reference stations "Aanestad A & B"

Corner History:

9-1853 Gov't Notes: 0.43 creek 50 lks wide runs SE. 18.00 same creek and enter timber bears NE. 19.00 creek 40 lks wide runs NE. 26.50 same creek 40 lks wide runs SE. 27.50 leave timber and enter prairie bears NW. 40.00 set QR sec post. Burr Oak 10 N 83° W 285 lks. Burr Oak 10 N 57° E 107 lks.

6-1875 T. Hunter (P.283 No.280) corner gone, bearing trees gone. Much brush and high river at this time. Meas East from SW cor 33 see P.282 40.00 for line North.

6-1877 T. Hunter (P.319 No.313) corner gone as well as all corners from. NW cor 3 104-15 (stone in post hole averred) to SE cor 33 (a stake in mound). Corner must come 40.13 from section corners E & W and record says gov't notes 5.35 East of NW cor 3. In other words corner really never set just passed over.

1935 county highway department B.79 found nothing used fence corner.

11-22-1993 County Surveyor dug for T. Hunter stake set 2640' from West. Found post hole .60' West of T.N. also gray spot running into clay .65 E and .10 North of T.N. We found a 2" diam. black soft spot running 7" to 8" into clay ± .60 West and ± 3.1 North of T.N. We dug South to cover T.H. distance from center of section 33. Found post stub at clay height running 2' deep in clay. The oldest post of these that we found it was ± 2' S and .5 West of T.N. We also found a 3" diameter smaller at end. This is ± 4' S of T.N and ± 1' East of T.N.

7-18-2002 County Surveyor set 6' telspar pipe w/Cast Iron cap up 0.2' at the 2" diameter mark found 0.06 West and 3.1' North of traverse nail on 11-22-93. Accepted this mark as the location of Hunters stake since it was very near the line from the stone found at South section cor. 32-33, T105N, R15W projected over the stone found at the 1/16th East of the North quarter corner of section 4, T104N, R15W and very near the distance from stone found at the North quarter corner of section 4, T104N, R15W over the stone found at said 1/16th corner.

11-10-2011 County survey crew found cast iron cap in good condition