Certificate of Location of Government Corner

ID#: 553309 **Description:** SEC CEN 33 55 **Date Set:** **County:** Olmsted

Section: 33 **Township:** 105N **Range:** 15W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.

5/8" Pipe with Cap No. 41814

Reference Ties:

The monument is down 0.4'
The monument falls 1' north of centerline twp road and in line with common line north.
This corner is located by GPS measurement

Corner History:

6-9-1875 T. Hunter (P.283 No.280) set stake at inters lines. 1/16 North set stake M&L 20.02 (1321.32) N 10' W to true corner. 1/16 East set stake M&L 20.02 (1321.32) S 89 1/4 W to true corner. 1/16 West set stake M&L 19.83 3/4 (1309.27) to true corner. 1/16 South set stake M&L 19.83 1/2 (1309.11) N 10' W to assumed cor 40 ch W SW corner.

6-25-1902 W. Fraser (P.21B) Hunters stakes found as follows. Set irons at all stakes.

7-27-1971 County Surveyor set 00 nail center T road and fence line South. Meas West to County corner at 1/4 32-33 set nails at center 33 at 2646.33 found post and iron at 3.2 E or 2642.83. 1/16 East 1406.8 found 1" x 18" iron at 1322.5 from 1/4 33-34. 1/16 West 3952.0 found iron bolt 5/8" x 12" at 3950.9 from 1/4 33-34. Total 5259.36. 00 nail found stone and iron 2.12 N and .3 W of nail at 1/4 33-34. Set 120d over iron and post found subject to slight changes such as 1/4 32-33 being 1.3 South as line suggests. CIM set at 1/4 33-34 as final. 2642.83 R. 2642.64 acceptable as OK for E-W for center if center used as N-S then 1/16 East should move E 1.09' and South .04. Center would move South about .12 must dig out 1/4 32-33.

12-1-2008 County survey crew found 60d spike at surface bent and leaning. Removed 60d spike and found 120d spke down 0.8' in good condition.

6-3-2011 County survey crew found 120d spike down 1.1'

4-18-2012 Massey Land Surveying set 5/8" pipe with cap at computed intersection of quarter lines

2-28-2013 County survey crew found 5/8" pipe with cap 41814 in good condition.