Certificate of Location of Government Corner

ID#: 553405 **Description:** S SEC COR 33 34 55 **Date Set:** 11/10/2011 **County:** Olmsted

Section: 34 **Township:** 105N **Range:** 15W **Monument Description:** Cast iron cap on telspar pipe

Reference Ties:

The monument is up 0.2'
The corner falls 1.5' west of corner post for fences north and west.
This corner is located by GPS reference stations "Hamilton A & B"

Corner History:

9-1853 61.40 creek 50 lks wide runs NE. 80.00 set post for corner to sec 33 and 34. Burr Oak 10 N 8° E 419 lks. Burr Oak 20 N 18° W 596 lks.

6-1877 T. Hunter (P.319 No.313) in survey sec 33 didn't find any sign of corner and brush and river made line a muddle so refered to this survey for setting of corner P.283 corner of course gone. Meas line from SE cor 34 to SW 33 making 80.26 for each mile established corner at that meas but not on direct line as gov't notes show it was not straight. Meas North to 1/4 33-34 40.25 as established which is limit for gov't error in chainage. Using this section corner as pivot established lines straight East to SE 34 to set corners East and straight line West to NW cor. Sec. 3 104-15 a stone found in post hole averred by Mr. Gordy as true cor. Set stake marked as corner. Which comes 4.89 chs East of N 1/4 S. 3 established M&L 40.02 on S. 3 (322.74')

9-23-2002 County Surveyor dug hole from c.p. 3' W x 2 1/2' N x 2 1/2' E. Found remains of old c.p. down 1 1/2' packed in stones. C.P. ran down to 2 1/2' to clean clay. Dug down 4' to rocky subsoil and found nothing. Old post is 1.7' W and 1.1' N of existing c.p.

12-16-2002 Olmsted County Surveyor computed a coordinate location for this corner with the preparation of Olmsted County Right of Way Plat No. 137 (although the actual corner is not graphically shown on the plat). It was computed by projecting a line from the north quarter corner of section 2-104-15 through the northwest corner of section 2-104-15 and equal distance between the southeast corner of Section 34-105-15 and the southwest corner of Section 33-105-15.

11-10-2011 County survey crew set 5' telspar pipe with cast iron cap from 12-16-2002 computed coordinates.