Certificate of Location of Government Corner

ID#: 553406 **Description:** 1/4 SEC COR 33 34 55 **Date Set:** 5/8/2009 **County:** Olmsted

Section: 34 **Township:** 105N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 2' north of centerline of CR 108, 3' west of centerline of twp road north and in line with fence south
Punched + in S end 24" CMP NE 62.8'
County Survey Disk in SE side PP #6275 SW 28.16'
County Survey Disk in NE side PP #6274 NW 30.95'
Concrete nail in SE side PP #6275 SW 28.06'
This corner is located by GPS measurement

Corner History:

5-1854 Gov't Notes M. Karrick 40.00 set quarter section post, dug trench. Bur Oak 10' N 58? 168

6-1875 T. Hunter P. 283 N 280 found stake, drove new stake well down with stone 7"x8"x14" on top of stake.

7-1893 W. Fraser found stone.

6-1902 W. Fraser found corner and set iron stakes.

8-5-1971 County Surveyor dug and found record size stone with iron below. Stone 5' deep. Set stone and iron back with 8" piece of chrome tail pipe over stone and CIM on top.

9-3-1993 County Surveyor found CIM in good condition.

12-1-2008 County Surveyor found Mag Nail at surface and removed. Found CIM down 1.2' in good condition.

5-8-2009 County Surveyor found CIM down 1.3' in good condition, took local ties and removed. Found chrome pipe down 2.9' w/top mangled, seemed to match local ties, removed. Probed to top of stone down 4'± did not dig up. Set 3 1/2' telspar pipe down 0.5' from ties taken from CIM.