# Certificate of Location of Government Corner

**ID#:** 553605 **Description:** S SEC COR 35 36 55 **Date Set:** 8/7/2002 **County:** Olmsted

**Section:** 36 **Township:** 105N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

**Reference Ties:**

The monument is up 0.2'
The corner falls 1' west of fence north, 3' south of electric fence east, 1 1/2' SW of CP and 48' west of bank of river
County Survey Disk in S side Box Elder E 9.15'
County Survey Disk in E side most N'ly twin Maple SE 22.30'
Post w/sign 1' east
This corner is located by GPS reference stations "Ironwood A & B"

**Corner History:**

9-1853 Gov't Notes Elisha Norris, Deputy Surveyor West on south boundary of section 36. 77.70 chs. Creek 75 lks. Wide runs N.E. 80.00 chs. Set post for corner to sections 35 & 36. Ash 10 in. N45°E 30 lks. Ash 6 in. N89°W 27 lks.

6-1878 Thomas Hunter (Book A, Page 350, No.342 and Old Field Book 5, Page 75) states: "Found stake standing by side of boyou. Tested it by stumps of witness trees found and found it correct." He set the N. 1/4 Cor. 1 4.80 chains West of this corner and on line from this corner to the N.W. Cor. Sec. 1.

5-1895 William Fraser, County Surveyor, (Book A, Page 574, No. 525) states. "Could find nothing of the stake at this corner as it had been washed out by high water, but Hunter gave a measurement from this corner to J (the N. 1/4 S corner of section 1, Town 104N, R15W) as 4.80 chains in survey (on Page 350) of Sec. 1, so we located corner at E (S. Sec. Cor. 35-36) 4.80 chains East of J and on line between J and I (N.E. Cor. 1)". He drove stake and planted stone as corner. He used this corner to set 1/4 Cor. 35-36 midway (40.02 1/2 chains) and on line between the section corners.

6-18-1971 County Surveyor found a large limestone here in boyou which was very near double the line and measure from Sec. Cor. 25-26-35-36 (found) over 1/4 Cor. 35-36 (found). We accepted this as Fraser's stone. Measured 4.80 chains West and found a small limestone standing under the E-W fence line at N. 1/4 Cor. 1.

6-8-1979 County Surveyor projected the line from the N.W. Cor. 1 (found) over the N. 1/4 Cor. 1 (found) and dug on this line at 4.80 chains East of the N. 1/4 Cor. 1. Did not find anything. We accepted this location as the closest to the original position as per Hunter's 1878 survey. We set a square pipe (telspar) with Cast Iron Cap at this point as the corner 3.41' North and .04' West of Fraser's corner found in 1971. Note: We used corners found at N. Sec. Cor. 1-2 and N. 1/4 Cor. 1, as Hunter found and set them, to establish this corner and not the N. Sec. Cor. 1-2 and N. 1/4 Cor. 1 as set this survey (See Certificates).

11-7-2000 County Surveyor found corner gone. Found post w/sign and checked ties. New corner post for fence N & E about 1' east of corner location. Corner probably got removed when new CP was placed.

8-7-2002 County Surveyor set 4' telspar pipe w/cast iron cap up 0.2' at computed position from GPS & traverse data.

11-10-2011 County survey crew found cast iron cap in good condition