Certificate of Location of Government Corner

ID#: 553606 **Description:** 1/4 SEC COR 35 36 55 **Date Set:** 6/29/2007 **County:** Olmsted

Section: 36 **Township:** 105N **Range:** 15W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 2' west of centerline of CR 115 north and 10' north of centerline of CR 108
16d nail in NW side TP SW 43.77'
Bottle cap in NW side PP #6351 NE 46.85'
This corner is located by GPS measurement

Corner History:

5-1854 Michael Karrick 40.00 set quarter section post. Burr Oak 8 S 43 W 510. Burr Oak 10 N 20 E 110.

1895 W. Fraser (BK. A pg. 574) found the corner gone so he set a stone 3" by 12" by 12" beside the stake.

1906 C. Armstrong (BK. B pg. 106) found the stone.

1924 County Hwy. Dept. (BK. 39 pg.40) found the stone.

6-21-1971 County Surveyor found the remains of the old stake and recorded stone. Set 1/2" pipe thru stake remains as true corner and left original stone.

6-21-1971 County Surveyor set CIM over 1/2" pipe as final corner.

6-28-2007 County Surveyor found CIM down 1.7' in good condition.

6-29-2007 County Surveyor removed CIM and found 1/2" pipe down 3.2' in good condition with stone on east side down 4'. Removed 1/2" pipe and set 4' telspar pipe w/cast iron cap down 0.5' at CIM position.