Certificate of Location of Government Corner

ID#: 600706 **Description:** W 1/4 SEC COR 7 60 **Date Set:** 9/26/2003 **County:** Winona

Section: 07 **Township:** 106N **Range:** 10W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in line with fence row north, 2' north of fence west and 6 1/2' south of fence row east
Post w/sign 6' NE
This corner is located by GPS reference stations "Klassen III & IV"

Corner History:

1853 Gov't Notes: N 40.00 chains, set quarter sec post in mound with trench and pitts and deposited charred stake and hawthorn seeds.

7-1890 Thos Fraser (P.444 No.429 S.12) C. Carter and others. Corner missing, Carter avers fence running west was on line fron original corner. A boulder 5 rods west under fence was originally on line so projected fence line over boulder and intersected township line between section corners of sec 12 and set 10x14x36 boulder as corner.

10-10-1974 Found corner on S side cor post, about 6" deep. Set a steel post on the SW side of the stone. Left the corner as is and did not set a CIM.

3-1980 Roger Brand, fence corner about 1/16 south ± 1' south and 4' west of comp 1/16th (1305.51-1305.51) set 3/4" iron pipe with elbow on tip at 1/16 north fall 7' north of fence east and 1.0' west of N-S fence. By measurments to 1/4 line sec 7 corner 1.8 ± west of st line between NW 7 and SW 7 as used this survey.

3-1983 County Surveyor (RWB survey in sec 7-106-10) Found greenish colored pointed boulder stone, down 6" on west side of newer corner post. Fences W&N no fences south or east at this time. Set 1/2"x9" iron pipe over point of stone. It is ± 1.0' W of center of cor fe post no other ties taken. Should get CIM in here and measre E line of sec 12 and compare to Thomas Fraser.

4-12-2000 County Surveyor found 1/2" x 9" iron pipe laying flat. Found greenish colored pointed boulder stone down 0.3'.

9-26-2003 County Surveyor found boulder at surface. Took ties and removed. Set CIC on a 6.0' telspar pipe down 0.5' at boulder location.