Certificate of Location of Government Corner

ID#: 601906 **Description:** W 1/4 SEC COR 19 60 **Date Set:** 11/2/2006 **County:** Winona

Section: 19 **Township:** 106N **Range:** 10W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 69' south of centerline of CR 142 and 68' east of centerline of farm driveway south
County Survey Disk in E side PP NNW 38.90'
Punch cross in S end culvert N 54.1'
Post w/sign 2' south
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes: N 40.00 chains set quarter sec post. B.T.'s - Burr Oak 10" N48°W 233 links, Burr Oak 12" S85°E 256 links

6-1857 John Fraser (P.30 No.47) only early survey, who at that time completely sub-divided section, all original corners set. Meas north and south 39.90 2633.4. 1/16 west 19.93 4 times to W 1/4 cor

1869 T. Hunter, RR tie 36.42 chains from northeast 24 south to center rails 2403.72 now 2 tracks west of St.Charles evidently mail line in north track.

7-1919 county highway department (B.28 P.47) 1/4 corner on county line station 564 + 41.8 from west. Corner is 81' south of south main track of RR north and 78' between RR tracks which is 2 main tracks, likely centers of tracks 2403.72 + 78 + 81 2562.72? John Fraser 1856 2633.4 P.30A. RP's - TP SE 62.3, TP SW 93.3.

1-7-1972 County Surveyor found nail set by McGhie on line from east. Found section corners at E 13-24 and E 24-25. Noted meas of nail from north and south.

5-9-1972 County Surveyor dug entire area with rented backhoe finally found large, very vertical limestone 4x10x24 (down 48") in level meadow lands, soils over stone field fill from lands south and west. Set cast iron sash weight on S side, buggy axle on N side, bent 1-1/4 pipe on W side. Set 1"x3' iron bar riser as temp corner. Corner .58' E of direct line of section corners .12' N of midway. 28.1' N of McGhie line from east. 2634.46 N to section corner E 13-24, 2634.7 S to section corner E 24-25. 218.0 SSW to center huge oak. 139.5' W to center huge pine with tuning fork shaped crotch, top half of tree. 84.4' (84.36) NW to punched cross in center W end farm drive culv (8-14-87 culvert in place but burned). NNW to pepsi cap on W side power pole with farm elec transformer (gone 8-14-87). 54.1 N to punched cross in westerly of 2 rivits in top of new 48" south end road culv.

6-11-1974 County Surveyor set CIM over 1/2" x 18" rerod down 0.5'.

8-14-1987 County Surveyor found CIM ok. CSD in E side PP NNW 39.05'. CH 57' to centerline E-W road. CH 225' N (due N) to centerline tracks.

4-7-2000 County Surveyor found CIM in good condition.

7-7-2006 Roger W. Brand found CIM without head down 1.1' in good condition. Set 1' telspar pipe w/cast iron cap down 0.1' over CIM.

10-31-2006 County Surveyor found cast iron cap on telspar pipe down 0.1' with loose cap in good condition.

11-2-2006 County Surveyor removed cast iron cap on telspar pipe and found CIM without head down 1.2' in good condition. Removed CIM and found 1/2" rerod down 2.8' in good condition. Removed 1/2" rerod and probed stone down 4.2'. Set 4' telspar pipe w/cast iron cap down 0.1'. Set post w/sign.

3-22-2007 County Surveyor found cast iron cap on telspar pipe down 0.2' in good condition.