Certificate of Location of Government Corner

ID#: 610305 **Description:** SEC COR 3 4 9 10 61 **Date Set:** 6/17/2011 **County:** Olmsted

Section: 03 **Township:** 106N **Range:** 11W **Monument Description:** Brass plug in concrete road

Reference Ties:

The corner falls 0.2' west of centerline crack of CSAH 10 and in centerline of E-W township road.
The monument is at the surface.
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes, William A. Jones, Deputy Surveyor North between sections 9 and 10. 80.00 chs. Set post at corner to sections 3,4,9,&10 Made mound, trench, and pits, and planted Cherry seeds S.W. & N.E., S.W. & N.W.

9-1857 E.P. Bircher, Surveyor, per T. Hunter, Deputy, (Old Road Book, Road No. 24) surveyed the N-S road here. Measured 39.50 chs. North to ¼ Cor. 3-4 and 40.00 chs. South to ¼ Cor. 9-10.

1925 county highway department (County Highway Department Book 36) assumed corner at center of intersection, set hub.

1944 county highway department (C.H.D. Book 168, 169, 171) shows hub and disc at the corner.

10-12-1983 & 10-13-1983 County Surveyor dug in the center of the intersection for the corner. Found a 1½"x19" pipe beneath blacktop. Found a 2"x2" hub with a spike in the top and several spikes around it 3½' deep and .26' North of pipe location. Found a 2½"x12"x13" limestone standing with top in old road 3.3' deep and base in clay. Drove a 1"x32" pipe on the East side of the stone and put scrap iron around it. Stone 2.41' South and .98' West of the pipe location.

10-19-1983 County Surveyor set a Cast Iron Monument over a 1" square x 1' pipe over the stone found as the corner.

3-21-2003 Roger Brand found monument in good condition.

3-7-2007 County Surveyor found CIM down 0.5' in good condition.

6-17-2011 Construction of CSAH 10 destroyed existing monument. County survey crew set a brass plug in concrete road using previous GPS coordinates