Certificate of Location of Government Corner

ID#: 610609 **Description:** SEC CEN 6 61 **Date Set:** 4/18/79 **County:** Olmsted

Section: 06 **Township:** 106N **Range:** 11W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.
3/8" iron rod

Reference Ties:

The monument is up 0.1'
The corner falls in line with fence south and 5' north of fence east.
Spike in 10" Burr Oak NW 30.85'
Center 16" Burr Oak in fence N 23.5'
Spike in PP SW 8.05'
This corner is located by GPS measurement

Corner History:

5&8-1887 T. Hunter (P.419 No.408) set marked stake at true inters lines. 1/16 north set stake on line N 1/4 cor at prop dist 5 lks short of gov't recording 19.97'1/2 north then 19.87-1/2. 1/16 south set stake 20.01 M&L.

4-17-1979 County Surveyor shot spike between 2 corner posts at center 6, a spike 173-1/2' east of the fe corner at the 1/16 S of center and a spike 38.2 east (in E-W fe) of a bent over 3/4" iron found near the 1/16 north of the center 6 (this iron was at the corner of fences W-S-E)

4-18-1979 County Surveyor dug at the center 6 drove at the calc intersection of 1/4 lines. Found a 8" diameter dark spot with wood remains. Set a 3/8"x18" iron rod with 3/4"x8" rod along south side. Set 2 stones one north and one south. The mark is 4.53' north and .1' east of the traverse nail set between the corner posts. RP's: Spike in 10" Burr Oak NW 30.85' center 16" Burr Oak in fence north 23.5', spike in power pole SW 8.05'. Straightened the iron (7/8"x30"±) found bent over at the 1/16 north of the center 6. It would have stood 36.7' west and 1.1' south of the traverse nail. Dug down and found it along the east edge of an old post hole. If the corner were set it would have to go appx 2.16' east and 2.50' south. RP's to iron: Center 18" Oak west 17.7', center cor post east 14.0', center 28" Burr Oak NNW 27'

6-28-2011 County survey crew found iron rod in good condition