Certificate of Location of Government Corner

ID#: 610704 **Description:** 1/4 SEC COR 7 18 61 **Date Set:** 7/16/1980 **County:** Olmsted

Section: 07 **Township:** 106N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 33' south of centerline of E-W twp road and in line with fence south
SW corner of concrete floor of patio deck NE 115.35'
County Survey Disk in E side of fence post N 8.01' (leaning)
Post w/sign 1' south
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, William A. Jones, Deputy Surveyor East on true line between sections 7 and 18. 39.58 chs. Set post at quarter section corner. Deposited handful charcoal. Made mound, trench and pits and planted cherry seeds N.E. and S.W. 79.58 chs. To section corner.

12-1890 Thomas Fraser, County Surveyor, (Book A. Page 450, No. 434) could find nothing at this corner or Sec. Cor. 7-8-17-18 though searched carefully.

6-1900 Robert Fraser (P. 686, No. 610, Book A) measured from W. Sec. Cor. 7-18 to Sec. Cor. 8-9-16-17 to set Sec. Cor. 7-8-17-18 (E-W) at proportionate Gov't measure. He overran 16 links making the North line of Sec. 18, 79.66 chs.

7-16-1980 County Surveyor set a telspar pipe with Cast Iron Cap as the corner in line with the fences South and North and at double the measure from the computed location of the Center 18 over the E-W fence at the 1/16 North. This corner is appx. 6.3' South of a straight line between the section corners. We also doubled the measure from the computed Center 7 over the fence East at the 1/16 South, but this would place the corner appx. 10' further South than as set. There is a yard fence North on the North side of the road which the people living N.E. of the corner say replaced the old fence running North. The old plat book show that the road here once went North to the 1/16 North and then went East so we decided the fence at the 1/16 North could be less reliable than the fence at the 1/16 South. Measure East 2629.18 to Sec. Cor. 7-8-17-18 and West 2622.96 to W. Sec. Cor. 7-18.

5-1983 County Surveyor found monument in good condition. Set survey marker on post 0.8' south of monument.

3-20-2007 County Surveyor found telspar w/CIC up 0.2' in good condition.