Certificate of Location of Government Corner

ID#: 610706 **Description:** W 1/4 SEC COR 7 61 **Date Set:** 4/23/1979 **County:** Olmsted

Section: 07 **Township:** 106N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 12' west of centerline of N-S twp road and in line with fences east and west
County Survey Disk in top of CP W 17.71'
County Survey Disk in TP SW 25.30'
W end field tile in ditch ESE 45.70'
County Survey Disk in W side PP #111 SE 118.35' (slope)
This corner is located by GPS measurement

Corner History:

9-1853 Gov't Notes, John Ball, Deputy Surveyor North between sections 7 and 12. 40.00 chs. Set post and drove charred stake for ¼ section corner. Built mound with trench per instructions and planted S.E. Osage orange and N.E. apple seed.

9-1857 E.P. Bircher, Surveyor, and Thomas Hunter, Deputy, (Road No. 101) surveyed a road along the town line but made no call for this corner.

6-1875 Thomas Hunter, County Surveyor, (Book A. P. 281 No. 278) found stake in old mound. Left as found. Used this corner to set the Center 12.

10-30-1877 T. Hunter (Book A Caption P. 281) set the 1/16th West of the Center 12.

9-19-1975, 9-24-1975 County Surveyor set a temporary point midway and on line between the section corners. The point fell on the west shoulder of the N-S road and in line with the fences East and West. Dug at this location with the backhoe but did not find anything.

4-23-1979 County Surveyor traversed the E-W ¼ line of section 12 tying in the West ¼ Cor. 12, the corner post at the Center 12 and the corner post at the 1/16th East of the Center 12 and the fence at the East ¼ Cor. 12. Found this line to be very straight. Set a Cast Iron Cap on a square 3' pipe as the East ¼ Cor. 12 midway (which falls in line with the fences East and West) and on line between the section corners. The corner is 12' West of the center of the N-S road here; however, the road does not follow the section line closely being 5' East at the S.E. Cor. 12 and 10' East at the N.E. Cor. 12. Also, the location as set agrees with the location of the N-S fence at the 1/16th East, a property line since the 1800's.

6-13-2002 County Surveyor found cast iron cap on telspar pipe down 0.4' in good condition.

4-5-2007 County Surveyor found telspar pipe w/CIC down 0.4' in good condition.