Certificate of Location of Government Corner

ID#: 610906 **Description:** 1/4 SEC COR 8 9 61 **Date Set:** 7/29/2008 **County:** Olmsted

Section: 09 **Township:** 106N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 4' west of fence north and 2' north of centerline of E-W twp road
3/4" iron pipe under fence N 50.15'
East edge tele cable warning post SE 49.45'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, William A. Jones, Deputy Surveyor North between sections 8 and 9. 40.00 chs. Set section corner post. Made mound, pits, trench, and planted cherry seeds.

6-1900 Robert Fraser (P. 686 Book A), County Surveyor, could not find stake claimed as corner. Set a dry oak stake with small stone beside it as corner midway and on line.

9-13-1973 County Surveyor found 10" of recorded wood stake. Removed stake and set 5/8"x30" iron.

11-28-1973 Roger Brand, County Surveyor. Set CIM over 3/8"x16" rod as corner.

10-1983 County Surveyor found CIM with head broken off, left as found.

7-29-2008 County Surveyor found CIM w/head broken down 0.5'. Took local ties and removed. Found 3/8" iron rod down 2.2' in good condition and matched ties. Set a 6' telspar w/CIC down 0.5' over rod.