Certificate of Location of Government Corner

ID#: 611006 **Description:** 1/4 SEC COR 9 10 61 **Date Set:** 6/17/2011 **County:** Olmsted

Section: 10 **Township:** 106N **Range:** 11W **Monument Description:** Brass plug in concrete road

Reference Ties:

The corner falls 0.2' east of centerline crack of CSAH 10, in centerline of E-W twp road.
The monument is at the surface.
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes, William A. Jones, Deputy Surveyor North between sections 9 and 10. 40.00 chs. Set post at quarter section corner. Made mound, trench, and pits, and planted Cherry seeds S.W. & N.E., S.E. and N.W.

9-1857 E.P. Bircher, Surveyor, per T. Hunter, Deputy, (Old Road Book, Road No. 24) surveyed the N-S road here. Measured north 40.00 chs. to Sec. Cor. 3-4-9-10 and south 40.00 chs. to Sec. Cor. 9-10-15-16.

1925 county highway department (C.H.D. Book 36) assumed corner in the center of the intersection. Set hub. Measured 2649 north to hub
in center of intersection at Sec. Cor. 3-4-9-10.

1944 county highway department (C.H.D. Book 168, 169, 171) surveyed the N-S road here. Shows 60d spike at corner, apparently at or near 1925 location by similar alignment from the north.

9-1980 Ron Olson, Surveyor, set P.K. nail for corner at location of iron detected (with magnetic locater). Point in center of N-S road and in center of road East. Used point for survey in SE¼ Sec. 9.

12-1980 Delmar Schwanz, Surveyor, may have used this corner to establish E-W ¼ line Sec. 9 for a survey in the SW¼ Sec. 9 (information not on File.)

6-1981 Jerome Schwarz, Surveyor, may have used this corner to set the Center 9 for a survey in the SW¼ Sec. 9. (Information not on file). Set ½" iron pipe with cap at Center 9.

10-12 & 13-1983 County Surveyor dug at location of P.K. nail found in the center of the intersection. Found a railroad spike between layers of blacktop .14 south and .44 west of the P.K. Found a 1" x 32" pipe (removed) beneath blacktop .36 south and 1.54 west of the P.K. Found nothing further. Road in cut here. Fill to clay 2' deep. Found Scharwz pipe at Center 9 to be on line from P.K. to the W. ¼ Cor. 9.

10-20-1983 County Surveyor set a Cast Iron Monument over a 3/4" re-rod at the location of the (Ron Olson) P.K. nail found here. Since intersection in road cut, the original corner has been destroyed. However, our survey indicates the center of the intersection here has not changed since 1925 and this location also holds the property line fence at the 1/16 North very near midway to Sec. Cor. 3-4-9-10 so accepted center of intersection as best evidence of corner location and specifically used P.K. since this the common point of Scharwz and Olson surveys.

3-7-2007 County Surveyor found CIM down 0.5' in good condition.

6-17-2011 Construction of CSAH 10 destroyed existing monument. County survey crew set a brass plug in concrete road using previous GPS coordinates