Certificate of Location of Government Corner

ID#: 611305 **Description:** SEC COR 13 14 23 24 61 **Date Set:** 9/12/2011 **County:** Olmsted

Section: 13 **Township:** 106N **Range:** 11W **Monument Description:** Cast iron cap on telspar pipe

Reference Ties:

The monument is up 0.3
The corner falls in line with fences E-W-N and in line with E-W PP line
County Survey Disk in N side PP E 13.15'
Post with sign 2' south
This corner is located by GPS reference stations "Rain Forest A & B"

Corner History:

9-1853 Gov't Notes, William A. Jones, Deputy Surveyor North between sections 23 and 24 80.00 chs. Set post at corner to sections 13, 14, 23 and 24. Stone 27"x15x2. Made mound of stones. This corner comes on stony point. Could make no trench.

5-1881 Thomas Hunter (P. 369 No. 360), County Surveyor, found original stake still in mound.

12-1894 William Fraser (P. 561 No. 515), County Surveyor, found stake in mound.

12-20-1974 W.H.K.S. found boulder 4"x15" sticking up 1' at fence corner to fences east, west, and north.

7-29-1975 County Surveyor found 4"x15"x30" weathered limestone up 15" with stake on west side (removed stake to office). Accepted stake as corner. Set ½"x12" rod in stake hole and set C.I.M. over rod. Left stone on east of monument. Corner in line of fences north, east, and west.

4-5-2000 County Surveyor found CIM at surface with head broken off.

7-23-2002 County Surveyor found CIM with head broken off.

9-12-2011 County survey crew found CIM with top broken at surface. Removed and found 1/2" rod directly below. Removed and replaced with a 3.5' telspar pipe with cast iron cap.