Certificate of Location of Government Corner

ID#: 611404 **Description:** 1/4 SEC COR 14 23 61 **Date Set:** 5/14/1992 **County:** Olmsted

Section: 14 **Township:** 106N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in line with E-W PP line and 3' west of N-S fence
County Survey Disk in PP ENE 5.53'
End north side wood fence post W 30.00'
County highway disk in W side wood fence post NNE 22.43'
County highway disk in S side PP ENE 5.48'
Sign on PP 5' east
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes, William A. Jones, Deputy Surveyor West on true line between Sections 14 and 23 39.97 chs. Set post at quarter section corner, deposited stone 4" x 4" x 2" made mound, trench and pits, planted cherry seeds NE and SW.

6-1857 John Fraser (page 44, No. 66) Used corner to set 1/16 corner east.

1869 Thomas Hunter 36.76 chs. south to centerline of railroad.

5-1881 Thomas Hunter, Deputy County Surveyor (page 369 No. 360) Found two stones between two stakes, to be within a foot of midway, set quarry stone on top of old stones found. Measured west 39.86 chs. Set 1/16th stone east 19.33 3/4 chs. midway and on line. Set center of section 23, 13" x 6" x 8" stone in this survey.

3-1900 Thomas Fraser, Deputy County Surveyor (page 655, No. 584½) Surveyed the SE ¼ section 14. Found boulder stone under the two quarry stones by side of two posts on NW side. Measure east 20 links short, 1/16 east found limestone as set in former survey, down 12" left as found.

11-26-1991 County Surveyor dug to cover N-S ¼ line in section 14 and 23 also Thomas Hunter measure E and W. This spot was 3½' west of N-S fence and in a field drive lane, spot was low and worn out. Dug for 1/16th stone north set by William Fraser in 1902 midway and on line. This spot was 8½' west of N-S fence, found nothing. Appears it would have been plowed out.

5-14-1992 County Surveyor set telspar pipe with cast iron cap, at Thomas Hunter prorated position and on line between section corners.

2-8-1993 Mn/Dot Found cast iron cap on telspar pipe and took new references.

7-15-2002 County Surveyor found cast iron cap on telspar pipe in good condition.