# Certificate of Location of Government Corner

**ID#:** 611504 **Description:** 1/4 SEC COR 15 22 61 **Date Set:** 12/2/2004 **County:** Olmsted

**Section:** 15 **Township:** 106N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

**Reference Ties:**

The corner falls in line with fence east, 1' east of fence north and 2 1/2' SE of PP
County highway disk in N side wood fence post W 1.00'
County highway disk in S side PP NW 1.75'
Sign on PP 1 1/2' NW
This corner is located by GPS measurement

**Corner History:**

10-1853 Gov't Notes, William A. Jones, Deputy Surveyor West on true line between sections 15 and 22. 39.91 chs. Set post at quarter section corner. Made mound, trench & pits, and planted cherry seeds N.E. and S.W. 79.82 chs. To section corner.

9-1889 Thomas Fraser, County Surveyor, (Book A, Page 435, No. 422) "Found large flat stone as corner about 30 in. long and 3 wide near and between old and new fence post. A very large boulder on North side of it." He used this corner to set the Center 22.

5-1895 William Fraser, County Surveyor, (Book A, Page 568, No. 520) "Found corner as given in Survey 422, Page 435." He projected the line South from this corner over the Center 22 (which he found) to set the S. ¼ Cor. 22.

8-1963 John Kerr, County Surveyor, (Kerr Book 87, Page 41) found a boulder at this corner and set a C.I.M. over it. He also dug at the Center 22 and found an oak stake that had small limestones set on edge around it. He set a C.I.M. here also.

10-15-1979 County Surveyor found Kerr's C.I.M. with the top broken off. Removed the C.I.M. and found it was set over a 7"x9"x17" boulder. Set the boulder back at its location, drove a ½" rod on its East side, and set a new C.I.M. over it. Note: Kerr's C.I.M. is on the West side of a large boulder. Since Thomas Fraser described this corner as being on the South side of a large boulder, since the dimensions of Kerr's stone do not fit the dimensions of Thomas Fraser's stone, and since the line from the S. ¼ Cor. 22 over the Center 22 (found by Kerr) falls appx. 2½' East of Kerr's C.I.M. at ¼ Cor. 15-22, we dug from the C.I.M. East along the South side of the large boulder but did not find anything.

9-6-1995 Mn/Dot found CIM and took RP's, CND E side wood fence post SSW 19.88', CND N side wood fence post SW 1.00', CND S side PP NW 2.00'.

9-2-2004 County Surveyor found CIM down 0.3' leaning east.

12-2-2004 County Surveyor removed corner post and took local ties to leaning CIM. Removed CIM and found stone. Removed stone and set 5.0' telspar pipe with CIC at stone location.