Certificate of Location of Government Corner

ID#: 611505 **Description:** SEC COR 15 16 21 22 61 **Date Set:** 1/12/2006 **County:** Olmsted

Section: 15 **Township:** 106N **Range:** 11W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 1 1/2' west of centerline of CSAH 10
County Survey Disk in SE side PP SW 41.43'
This corner is located by GPS reference stations "Whatever & Fountain"

Corner History:

1853 Gov't Notes: J. Ball set section corner post 80 chs north of 21-22-27-28.

5-1891 Thos Fraser (P.447 No.432) corner came in bridge abatement area. 9 lks SW of SE corner bridge. 1/16 west set stake 20.03-1/8 M&L 1322'± Co. Hwy. Dept. cross chiseled in bridge + right bridge curb 10.6, + left bridge curb 10.6, + south end bridge 37.5. Hunters RR ties 5.40 chs south to centerline rails, 15.36 chs west to centerline rails.

7-22-1975 County Survyeor at 1/16 W found 2"x14" (base) x14" limestone coming to point 1' deep and 1' east of new 5" corner post. Bent 1-1/4" flat iron around stone and set 1-1/4"x24" flat iron on east side with top over stone.

9-8-1986 County Surveyor found that point falls under bridge 17' ± N of face of S concrete bridge abutment area appears to have been dug out of south creek bank and probably cut several feet. Dipped and dug 3' diam hole 2' deep (all mud) found nothing. Believe no chance for cor.

1-12-2006 County Surveyor set 1" square pipe w/cap at surface from GPS and traverse data.