Certificate of Location of Government Corner

ID#: 611506 **Description:** 1/4 SEC COR 15 16 61 **Date Set:** 6/17/2011 **County:** Olmsted

Section: 15 **Township:** 106N **Range:** 11W **Monument Description:** Brass plug in concrete road

Reference Ties:

The corner falls 0.2' west of centerline crack of CSAH 10 and in centerline of E-W township road.
The monument is at the surface
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes, William A. Jones, Deputy Surveyor North between sections 15 and 16. 40.00 chs. Set post at quarter section post. Made mound, trench and pits, and planted cherry seeds N.W. and S.E.

7-1885 T. Hunter (P. 400 No. 390), County Surveyor, found old stake found earlier by John Fraser. Set 4"x10"x26" limestone.

9-1892 Thomas Fraser (P. 497 No. 467), County Surveyor, found stone in the center of the road as described by Hunter.

1944 county highway department (B. 168 P. 7) had a pipe in the blacktop.

7-14-1975 County Surveyor dug in intersection with backhoe and found recorded stone and stake (on East side). Found ½"x9" pipe 2.5'S and .25'W at surface and 3/4"x28" pipe 3.0'S and .5'W down 1'. Removed both. Removed stake to office. Set 1"x36" rod in the stake hole.

7-17-1975 County Surveyor set C.I.M. over 3/4"x28" pipe over all.

7-28-1999 County Surveyor found CIM 9" deep in blacktop CR #10.

7-26-2002 County Surveyor found CIM down 0.7' in good condition.

6-17-2011 Construction of CSAH 10 destroyed existing monument. County survey crew set a brass plug in concrete road using previous GPS coordinates