Certificate of Location of Government Corner

ID#: 611606 **Description:** 1/4 SEC COR 16 17 61 **Date Set:** 8/25/2004 **County:** Olmsted

Section: 16 **Township:** 106N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 7' south of centerline of E-W twp road and 1' west of centerline of residential driveway south
County Survey Disk in PP SE 37.69'
Top center 6"x6" TCM box NW 47.5'
County Survey Disk in NW side stub PP NE 46.05'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, Jones, Deputy Surveyor North between sections 16 and 17. 40.00 chs. Set quarter section post. Made mound, pits, trench, and planted cherry seeds.

9-1892 Thomas Fraser (P. 497 No. 469), County Surveyor, states all traces and evidence of corner gone. Placed boulder stone on line and 1/3 distance from N.W. Corner Section 16 and W. ¼ Cor. Sec. 21.

6-23-1975 County Surveyor dug with tractor and found boulder stone 8" x 10" 1' deep in W township road. Placed two bridge bolts and a small piece of C.I.M. beside stone and a 10" C.I.M. over all.

8-24-2004 County Surveyor found CIM without head down 0.5' in good condition.

8-25-2004 County Surveyor removed broken CIM and found 8"x10"x24" boulder stone down 1.3' in good condition. Removed boulder stone and set 5' telspar pipe with cast iron cap down 0.4'.