Certificate of Location of Government Corner

ID#: 611706 **Description:** 1/4 SEC COR 17 18 61 **Date Set:** 3/22/2007 **County:** Olmsted

Section: 17 **Township:** 106N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 8' east of centerline of CR 132 and 12' south of centerline of twp road east
SE corner of pole shed (metal corner) NW 172.0'
County Survey Disk in W side PP #47660 NNE 68.04'
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes, William A. Jones, Deputy Surveyor North between section 17 and 18. 40.00 chs. Set post at quarter section corner. Made mound, trench, and pits and planted Cherry seeds N.E., S.W., S.E., and N.W.

1890 Thomas Fraser (P. 450 No. 434), County Surveyor, states he could find no corner.

6-1900 Robert Fraser (P. 686 No. 610), County Surveyor, could find no corner.

1939 county highway department (B101 P. 6) assumed corner.

9-24-1975 County Surveyor dug 5' x 8' with backhoe. Found road had been cut to clay 1½' deep. Set C.I.M. over 5/8"x12" rod midway and on line as corner.

3-21-2007 County Surveyor found CIM down 1' leaning SE.

3-22-2007 County Surveyor found CIM down 1' leaning SE. Removed CIM and found 1/2" rerod down 2.4' in good condition. Removed 1/2" rerod and set 5 1/2' telspar pipe w/cast iron cap down 0.4' at 1/2" rerod position.