Certificate of Location of Government Corner

ID#: 611805 **Description:** W SEC COR 18 19 61 **Date Set:** 4/2/2007 **County:** Olmsted

Section: 18 **Township:** 106N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 2' west of centerline of N-S twp road and 230 1/2' north of centerline of CR 142
Bottle cap in PP #1691 NNE 130.17'
PK nail in centerline of CR #142 S 230.10'
GPS point (Graham) SW 32.35'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes, John Ball, Deputy Surveyor North between sections 19 and 24. 80.00 chs. Set section corner post. Built mound, drove charred stake, dug trench, and planted osage orange and apple seeds.

7-1874 Thomas Hunter (P. 257 No. 257), County Surveyor, found old stake. Set stone on sides of stake.

1890 Thomas Fraser (P. 450 No. 434), County Surveyor, found stone replaced by settlers after being torn out by road grading. Reset 3"x12"x26" stone.

9-10-1973 County Surveyor found recorded limestone. Set C.I.M. over iron over stone.

6-8-2001 County Surveyor found CIM down 0.4' in good condition.

6-17-2002 County Surveyor found CIM w/head broken off down 0.5' in good condition.

4-2-2007 County Surveyor found CIM with head broken down 0.5', took local ties and removed. Found 1/2"x12" iron rod down 2.2' in good condition, took local ties, ties matched CIM. Removed some bedrock and set 3 1/2' telspar pipe w/CIC down 0.5' from ties taken from CIM. Updated ties.