Certificate of Location of Government Corner

ID#: 612106 **Description:** 1/4 SEC COR 20 21 61 **Date Set:** 3/23/2007 **County:** Olmsted

Section: 21 **Township:** 106N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls 22' west of centerline of N-S twp road and in line with fences east and west
County Survey Disk in E side PP SSW 82.05'
Post w/sign 2' west
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes, William A. Jones, Deputy Surveyor North between sections 20 and 21. 40.00 chs. Set post at quarter section corner. Made mound, trench, and pits, and planted cherry seeds N.E. and S.W.

5-1891 Thomas Fraser (P. 447 No. 432), County Surveyor, found stake by post claimed at location of original corner stake.

9-1892 Thomas Fraser (P. 497 No. 469), County Surveyor, found stake with stone by side.

10-1930 John Kerr (B. 4 P. 4-5), County Surveyor, found remains of old stake and fence post. Set 2"x4" stake 4' long and pit boulder with cross on W. side.

7-15-1975 County Survyeor dug with backhoe in West ditch N-S twp. road. Found boulder with cross and 2"x4" on east side as recorded by Kerr 2' deep. Set another large boulder on the east side of the 2"x4". Drove 1¼"x30" pipe (down 12") to retain location.

9-25-1975 County Surveyor dug 3'/9'x10' southwest of the pipe to cover Fraser's full measure from the north and the line between the section corners. Found nothing. Accepted Kerr's location, drove pipe down and set C.I.M. over all.

6-29-1995 Roger Brand found monument with top broken off. Corner post is now gone. Took new tie to nail in east side power pole SW 82.15

3-21-2007 County Surveyor found CIM with head broken off down 0.4'.

3-23-2007 County Surveyor found broken CIM. Took ties and removed. Found 1 1/4" pipe down 2.1' in good condition. Took ties and removed. Set a 5' teslpar pipe w/CIC down 0.2' at pipe location.