# Certificate of Location of Government Corner

**ID#:** 612205 **Description:** SEC COR 21 22 27 28 61 **Date Set:** 9/11/2006 **County:** Olmsted

**Section:** 22 **Township:** 106N **Range:** 11W **Monument Description:** 1" square pipe w/cap RLS #15809

**Reference Ties:**

The corner falls in centerline of CSAH 10 and 10' north of centerline of field drive west
NW corner of house foundation E 123.37'
NW corner of quonset shed foundation SE 158.5'
This corner is located by GPS measurement

**Corner History:**

10-1853 Gov't Notes, William A. Jones, Deputy Surveyor North between sections 27 and 28. 80.00 chs. Set post at corner to sections 21-22-27-28. Made mound, trench, and pits, and planted cherry seeds N.W. and S.E.

4-1871 Robert Perry (P. 182 No. 193), County Surveyor, found stone in the center of the road.

7-1886 Thomas Hunter (P. 414 No. 403), County Surveyor, found stone in the center of the road.

5-1895 William Fraser (P. 568 No. 520), County Surveyor, found stone.

1943 Co. Highway Dept. found stake over stone (B. 180 P. 76).

8-1961 Co. Highway Dept. (B. 240 P. 6) set C.I.M. at corner preserved with a pipe.

7-15-1975 County Surveyor dug down to verify Co. Highway Dept. C.I.M. Found road now cut to clay-nothing beneath C.I.M. Set 10" C.I.M. over one in place and accepted as corner location.

10-5-1979 County Surveyor dug with the backhoe from a point set up at Perry's measure from sec cor 21-22-27-28 and in centerline Co. Rd. 10 east 2', west 4', north 5', and south 5'. We dug through 11-1/2' of fill before getting to black dirt and at this depth with the time we had left we only got a look at a few square feet beneath the point set up. Found nothing. There was no old road on this black dirt and it was much deeper than we expected.

6-1-2004 County Surveyor found CIM down 0.6' in good condition. Set reference pipes and tied out corner.

6-13-2005 County Surveyor found CIM down 0.7' in good condition.

8-3-2005 County Surveyor found CIM down 0.4' in good condition. Removed CIM for overlays. Will replace with 1" square pipe after construction.

9-11-2006 County Surveyor set 1" square pipe w/cap at surface from reference angle.

3-21-2007 County Surveyor found 1" square pipe w/cap at surface in good condition.