Certificate of Location of Government Corner

ID#: 612206 **Description:** 1/4 SEC COR 21 22 61 **Date Set:** 9/11/2006 **County:** Olmsted

Section: 22 **Township:** 106N **Range:** 11W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 11' west of centerline of CSAH 10 and 20' north of centerline of field entrance west
Punch hole in top S end 18" CMP SW 40.02'
Punch hole in top N end 18" CMP WSW 21.56'
This corner is located by GPS measurement

Corner History:

9-1853 Gov't Notes, William A. Jones, Deputy Surveyor North between sections 21 and 22. 40.00 chs. Set post at quarter section corner. Made mound, trench, and pits, and planted cherry seeds N.W. and S.E.

7-1886 Thomas Hunter (P. 414, No. 403), County Surveyor, states corner gone and settlers disagree as to location. Set temporary corner midway and on line. Corner claimed still in road 3' deep. Did not look for it.

9-1889 Thomas Fraser, (P. 435 No. 422), County Surveyor, states corner gone and still in controversy. A Mr. Kimber avers stake once stood in line with fence west and on west road embankment.

5-1895 William Fraser (P. 568 No. 520), County Surveyor, found marked stake on west side of road.

7-10-1975 County Surveyor dug with tractor on W. shoulder of Co. Rd. 10 and found small limestone with wood stake 5' deep. Set 1½"x3' axle shaft with nut on top over stake. Set a C.I.M. over all.

9-12-1995 Mn/Dot found CIM

7-28-1999 County Surveyor found CIM in good condition down 1.3'

6-13-2005 County Surveyor found CIM down 1.4' in good condition. Set reference and tied out corner for 2005 overlays.

8-3-2005 County Surveyor found CIM down 1.4'. Broke off first section so it is deep enough for a 1" square pipe to be set over it. CIM is now down 1.7'.

8-28-2006 County Surveyor set pk nail at surface from 2005 overlay tie out.

9-11-2006 County Surveyor set 1" square pipe w/cap at surface over pk nail, updated ties.

3-21-2007 County Surveyor found 1" square pipe w/cap at surface in good condition.