Certificate of Location of Government Corner

ID#: 612304 **Description:** 1/4 SEC COR 23 26 61 **Date Set:** 9/22/2003 **County:** Olmsted

Section: 23 **Township:** 106N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The monument is at the surface
The corner falls 1' east of fence north and 3' south of E-W fence
Post w/sign 2' North
This corner is located by GPS reference stations "Storm A & B"

Corner History:

1853 Gov't Notes: J. Ball, set 1/4 section corner post M&L 19.93-1/2 2643.63. 10" Burr Oak S85W 315. 10" Burr Oak N62N 320.

6-1857 John Fellows (P.43 No.65) shows 1/4 post (see survey for interior breakdown of sec 26). John Fraser (P.44 No.66) shows 1/4 post meas east 40.25 chs, meas north 39.89 chs. 1/16 west 20.00 chs. (see survey for interior breakdown of sec 23).

5-1881 Hunter (P.369 No.360 S.23) found stone undisputed, planted as 1/4 corner B trees grubbed out and gone. 1/16 north, set stone M&L 19.93-1/2 1315.7. Set stone east of above 1/16 stone 9.95-1/4 656.87.

11-26-1991 County Surveyor dug for stone found by T. Hunter in 1881. This area is in a filter area from south we dug 3-1/2' deep to clay and water we probed extensively to cover 1/4 line from north and distance from center of 23, found nothing.

4-25-2003 County Surveyor set 2 points to determine location.

9-22-2003 County Surveyor set 6' telspar pipe w/Cast Iron Cap up 0.1' at 1/4 line from North and line location E-W. Set post w/sign 2' North.

4-26-2012 County survey crew found cast iron cap in good condition