Certificate of Location of Government Corner

ID#: 612305 **Description:** SEC COR 22 23 26 27 61 **Date Set:** 10/12/1979 **County:** Olmsted

Section: 23 **Township:** 106N **Range:** 11W **Monument Description:** Cast Iron Cap on telspar pipe

Reference Ties:

The corner falls in line with fences east and south and 1' west of CP
Sign on CP 1' east
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes, William A. Jones, Deputy Surveyor North between sections 26 and 27. 80.00 chs. Set post at corner to sections 22,23,26&27 Bur Oak 13 in. S11½°W 654 links Bur Oak 7 in. N10½°E 387 links Bur Oak 6 in. S69°E 194 links Made trench.

6-1857 John Fellows, Surveyor, (Book A, Page 43, No. 65) used this corner for a survey in Section 26.

6-1857 John Fraser, Surveyor, (Book A. Page 44, No. 66) possibly used this corner to set the 1/16th East.

8-1857 E.P. Bircher, Surveyor, per J.B. Fellows, Deputy, (Old Road Book-Co. Rd. No. 65) surveyed a road from Section Cor. 26-27-34-35 north on the section line to Sec. Cor. 22-23-26-27, and then north to ¼ Cor. 22-23.

5-1895 William Fraser (Book A. Page 568, No. 520), County Surveyor, "Found remains of old stake and post just west of corner post of fence now standing. We had to dig down about 3 feet to find stake as the earth has washed in and covered it. We drove stake not marked with boulders stones piled around." He set a stone at the 1/16th West midway (20.06 chs.) and on line to ¼ Cor. 22-27 which he also set in the survey. He set the 1/16th North midway (19.90 chs.) and on line.

10-12-1979 County Surveyor dug on the West side of the corner post to fences East and South as indicated by ¼ Cor. 22-27 (See Certificate filed) and Fraser's stone found at the 1/16th East. Found a circle of 5 small boulders 3' deep, but no stake remained. Set a square pipe (telspar) with a Cast Iron Cap in the center of the stones.

4-24-2003 County Surveyor found cast iron cap on telspar pipe in good condition.