Certificate of Location of Government Corner

ID#: 612309 **Description:** SEC CEN 23 61 **Date Set:** 6/25/1975 **County:** Olmsted

Section: 23 **Township:** 106N **Range:** 11W **Monument Description:** Note: Information regarding this center of section is provided for reference purposes only. A professional land surveyor should make the decision whether to use any existing survey monument or the computed intersection of quarter lines.
1" iron shaft

Reference Ties:

The corner falls 3' south of centerline of CR 142 and 101' west of centerline of farm entrance south
South edge of south rail of railroad tracks N 196.8'
County highway disk in PP #1526 SE 73.75'
County highway disk in S side wooden mailbox post ESE 123.40'
County highway disk in SW side PP #1526 SE 73.83'
County highway disk in W side 3" Maple SW 64.78'
This corner is located by GPS measurement

Corner History:

6-20-1857 John Fraser (page 44, No. 66) Used a center of section. Chained east 19.93 to 1/16th corner, chained west to 1/16th 19.93 and 19.93 to 1/4 corner, chained south 39.89 to 1/4 corner.

5-21-1881 Thomas Hunter, Deputy County Surveyor (page 369, No. 360) Set stone 13"x6"x8" at intersecting quarter lines. Set stone 1/64th corner east 9.95¼ chs. midway and online, 1/16th stone 19.90½ chs. east midway and on line, 1/16th stone west 19.91 chs. midway and online 1/16th stone south 19.93½ midway and online.

6-25-1975 County Surveyor dug with backhoe in road and found 8"x8"x13" limestone 4½' deep, 1' south of centerline of E-W road. 3' east of fence line north across highway 14, set 1"x36" iron shaft over stone. 1/64th corner east, dug with backhoe, found 4"x8"x18" stone 3' deep, 4' south of centerline of E-W road, set 3/4" rod over stone. 1/16th corner east found small boulder stone with stake on north side 3½' deep, 3' south centerline of E-W road, 5' west of centerline of road south and inline with fence north across highway 14. 1/16th corner West found 3"x6"x10" limestone 6½' deep on south shoulder of E-W road in field drive south, 16' south of centerline and 5' west of centerline of field drive.

3-31-1977 K. Ewers found and used 1" iron shaft.

1-15-1993 Mn/Dot Found 1" Iron and took references.

10-21-1998 County Surveyor found 1" iron shaft in good condition down 0.8'.

5-1-2003 County Surveyor found 1" iron shaft in good condition down 0.8'.

1-10-2004 Blumentritt Land Surveying found and used 1" shaft at center of section 23.