Certificate of Location of Government Corner

ID#: 612504 **Description:** 1/4 SEC COR 25 36 61 **Date Set:** 9/20/1995 **County:** Olmsted

Section: 25 **Township:** 106N **Range:** 11W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls 3' north of centerline of CSAH 29
Ref pipe SSW 82.58'
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes: Set corner 40.01 midway. Set post at quarter sec corner, deposited handful of gravel, made mound, trench and pits.

5-1881 John Fraser (P.370 No.361 S.25) N. Rubens, H. Taylor, found gov't corner post, no meas, no description. 1/16 west, plat shows corner in place, now county road with township road south.

1943 (B.180 P.76) corner assumed Co. H.D. Meas east 2643.25 west 2638.95 total mile 5282.2. P.5 B.180 set 1/2" rod at a point midway between fences found at 1/4 corners north and south, and in line with fence north for sec cor 25-26-35-36, then run line to sec cor east and assumed this 1/4 corner 25-36 on line and midway but set 2"x2" hub in line with fence running north and as P.O.T. on sec line as run, which is not midway sta. 132 + 31.75. P.17 B.180 Topog shows centerline Twp Road to south at sta. 132 + 26 and fence to north at sta 132 + 32 = 29' LT at sta. 132 + 49. Big row walnut trees 31' LT from Topog centerline travelled road appears as ± 5' S of centerline as run at sta. 145 + 53 = 1/16 fence runs north at 26' LT to cor of fence at sta. 158 + 75.0 = sec cor 25-36 on Co. line.

7-23-1980 County Surveyor road cut to bedrock at ± 24". Dug large hole across centerline of E-W road and in line fence north. A. Armstrongs iron (at E 25-36) and the 1/16 fence west agree with this location E-W. Found A.Armstrong's hub 31 ft out from the line of walnut trees on the N side of road. Continued digging south and found another 1"x2" gub and the whole area had been dug extensively. This hub was 6.1' south of Armstrong's 2x2 hub. Tied out both hubs until location can be proved further from 1/4 lines in 25 and 36. RP's - C.S. disc in top of corner post over C.H. dept disc NW 45.43'. C.S. disc in top of corner post SW 52.67' this hub is 3' north centerline. RP's to south hub - C.S. disc in top corner post NW 49.84'. C.S. disc in top of corner post SW 48.60' this hub is 3.0' south of centerline.

6-14-1995 County Surveyor set P.K. nail at Armstrong hub location 3' north of centerline CR #29 from traverse points used in 1980. The corner post ties are no longer any good. Set 1" sq. pipe w/cap on W shoulder N-S Twp road 82' south of the corner and 12' W of centerline N-S Twp road. Angle at ref pipe. Angle RT top center radio tower ENE to PK at 1/4 cor 25-36 287° 43' 16.5" to PK at 1/4 cor VA 90° 21' 17" dv 07 slope 82.58' HOR 82.58'

9-20-1995 county highway department set 1" square pipe w/cap at surface from 1995 overlay tie out.

4-24-2003 County Surveyor found 1" square pipe w/cap at surface in good condition.