Certificate of Location of Government Corner

ID#: 612505 **Description:** SEC COR 25 26 35 36 61 **Date Set:** 9/20/1995 **County:** Olmsted

Section: 25 **Township:** 106N **Range:** 11W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of CSAH 29 and in line with fence south
Ref pipe WSW 37.26'
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes, William A. Jones, Deputy Surveyor North between sections 35 and 36. 80.00 chs. Set post at corner to sections 25-26-35-36. Bur Oak 9 in. N45°E 137 lks. White Oak 7 in. S50°W 66 lks. Bur Oak 8 in. N40°W 48 lks. Bur Oak 6 in. S14½°E 62 lks.

6-1857 John Fellows, Surveyor, (Book A, Page 43, No. 65) possibly used this corner to set the 1/16 West (19.19 chs.). Measured North 40.00 chs.

5-1881 John Fraser, Surveyor, (Book A, Page 390, No. 361) possibly used this corner to set the 1/16 East.

9-1943 A. Armstrong (County Highway Department Books 180 and 181) "dug here but found nothing. ½ mile South of here we found fence corner with lots of hard heads around it but nothing to identify itself as a marker. I assumed fence corner to be ¼ corner. ½ mile North I found same thing and assumed fence corner to be ¼ corner. For purposes of this survey I set a ½" rod at Sec. Cor. 25-26-35-36 on line with the fence running South and midway (2634.4) between the two assumed ¼ corners." He set ¼ Cor. 25-36 (a 2"x2" hub) in line with the fence North and on line to E. Sec. Cor. 25-36 (a ½" rod set this survey).

7-24-1980 County Surveyor dug but the road had been cut to bedrock. Set a 5/8" rod as the corner on the line from Armstrong's iron found at E. Sec. Cor. 25-36 over Armstrong's 2"x2" hub found at ¼ Cor. 25-36 and in line with the fence south.

6-14-1995 County Surveyor, 5/8" Iron from 1980 was gone. We located this position from 1980 Traverse. Referenced this position before cold Recycling Bituminous Surface of CR 29.

9-20-1995 county highway department set 1" square pipe w/cap at surface from 1995 overlay tie out.

4-24-2003 County Surveyor found 1" square pipe w/cap at surface in good condition.