Certificate of Location of Government Corner

ID#: 612605 **Description:** SEC COR 26 27 34 35 61 **Date Set:** 9/20/1995 **County:** Olmsted

Section: 26 **Township:** 106N **Range:** 11W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The corner falls in centerline of CSAH 29 and in line with fence north
Punch mark in 3" pipe gate post NW 41.92'
County Survey Disk in E side PP SW 35.52'
Punch hole in E end CMP SE 34.08'
Ref pipe S 49.55'
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes, William A. Jones, Deputy Surveyor North between sections 34 and 35. 80.00 chs. Set post at corner to sections 26,27,34 & 35. Made trench & pits & planted Cherry seeds N.E. & S.W.

6-1857 John Fellows, Surveyor, (Book A, Page 43, No. 65) used the corner for a survey in Section 26.

8-1857 E.P. Bircher, Surveyor, and J.B. Fellows, Deputy, (Old Road Book-Co. Rd. 25) surveyed a road commencing at the S.E. Cor. Sec. 27, thence N0°5'W 40.00 chs. to ¼ S. bet. 26-27, thence N0°5'W 40.00 chs. to Cor. Sec. 22-23-26-27, etc.

1943 A. Armstrong (County Highway Department Bk. 180, Pg. 76) states "Wendell Coulson who has lived here for 30 years, showed us where the stone had been for many years. He said it was a pink boulder and was located in the center of the road and in line with the center of a track running north. The fence running north, he says, is not on the section line but about 12' East of the line. He also said the stone used to stick up in the road so that it was visible. After we had dug all around here and could not find the stone, he concluded that it must have been graded out. He again showed us the spot where the stone should be and said he was sure of its correctness within a couple feet at the most. Robert Larimer who lives West of the corner says that the stone used to set in the middle of the road about 4 or 5 feet west of the fence line. We dug all the way from the fence to a point 20' west, down to the ledge rock but found nothing." The County Highway Department used a point here appx. 12' west of the fence north and in the center of the E-W road. They measured West 2621.5' to ¼ Cor. 27-34 (assumed in line with the fence south), then 2631.1' to Sec. Cor. 27-28-33-34 (set this survey). They measured 673½' East to the fence South at the 1/64th East, a very old property line, 3970½' East to a fence North at the1/16th East of ¼ Cor. 26-35, a very old property line, and 5290.2' East to Sec. Cor. 25-26-35-36 (assumed in line with the fence running South).

10-2-1979 County Surveyor dug in the center of the E-W road and in line with the fence North. The area had been cut to rock and we did not find anything. A County Highway Department iron rod was found in place 12' West of the fence line North and in the centerline of the E-W road.

10-31-1979 County Surveyor set a C.I.M. over a ½"x8" rod, 12.0' East of the County Highway Department iron and in the centerline of the E-W road as the corner. Road construction here has obliterated the old corner. After measuring in sections 27 and 34 and considering the 1943 County Highway Department measurements to the property line fences in sections 26 and 35, we accepted lines of occupation, the center of the E-W road and the line of the fence North, as the corner location.

6-15-1995 County Surveyor found CIM in good shape, set ref pipe for road improvements.

9-20-1995 county highway department set 1" square pipe w/cap at surface from 1995 overlay tie out.

4-24-2003 County Surveyor found 1" pipe w/cap at surface in good condition.