Certificate of Location of Government Corner

ID#: 612606 **Description:** 1/4 SEC COR 26 27 61 **Date Set:** 10/4/1979 **County:** Olmsted

Section: 26 **Township:** 106N **Range:** 11W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 34' north of FAI-90 R/W fence
Cast Iron R/W Monument S 32.5'
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes, William A. Jones, Deputy Surveyor North between sections 26 and 27. 40.00 chs. Set post at quarter section corner. Deposited stone 6"x4"x2". Made mound, pits, and trench and planted cherry seeds N.E. and S.W.

6-1857 John Fellows, Surveyor, (Book A. Page 43, No. 65) used this corner for a survey in Section 26.

8-1857 E.P. Bircher, Surveyor, per J.B. Fellows, Deputy, (Old Road Book-Co. Road No. 65) surveyed a road from Sec. Cor. 26-27-34-35 north to ¼ Cor. 26-27, then north to Sec. Cor. 22-23-26-27.

4-1871 Robert Perry, County Surveyor, per Thomas Hunter, Deputy, (Book A. Page 182, No. 193) found stake as ¼ post under and in line of fence. He used this corner to set the 1/16th West and the Center 27.

1935 county highway department (C.H.D. Book 83, Page 74) "Found E. ¼ Cor." (no description)

11-1961 M.H.D. (survey for I-90) found in place hard head boulder at intersection fence corner 12" above ground (12"x15" stone). This corner tied to I-90 alignment.

10-4 & 10-1979 County Surveyor after construction of I-90 this corner falls in cultivated field and the fence corner here has been removed. Using M.H.D. I-90 data, the County Surveyor dug for the corner and found the remaining 28" of an old post packed in stones. Drove a 1"x23" drill steel at the post location. Set the C.I.M. over the drill steel with the post on the West side.

4-24-2003 County Surveyor found CIM 1.5' deep in CRP field in good condition.