Certificate of Location of Government Corner

ID#: 613004 **Description:** 1/4 SEC COR 30 31 61 **Date Set:** 9/20/1995 **County:** Olmsted

Section: 30 **Township:** 106N **Range:** 11W **Monument Description:** 1" square pipe w/cap RLS #15809

Reference Ties:

The monument is at the surface.
The corner falls 1' south of centerline of CR 129 and 3 1/2' east of fence north
County Survey Disk in PP #1813 NE 133.22'
County Survey Disk in PP #1810 NW 124.89'
County Survey Disk in W side 15" Pine SSW 48.08'
Ref pipe N 41.28'
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes, William A. Jones, Deputy Surveyor East on true line between sections 30 and 31 39.52 chs. Set post at quarter section corner made mound, trench, pitts and planted cherry seeds NE, SW, SE, NW

6-1863 P.C. Compton, County Surveyor (page 71, No. 102) Shows 107-11 but believe it to be Sec. 30-106-11. Set stone 5"x7"x9", 1/16th corner east 5"x11"x12", 1/16th corner north 5 1/2"x11"x20" with glass beneath center of section set 24"x15"x15" stone with glass beneath.

5-26-1977 County Surveyor dug with backhoe in road and found a 6"x9"x10" boulder with a flat top 3' deep with a stake hole below stone, set bolt on south side, and 1/2" rod on north side of stone. Set 1/2" rod over stone at surface. 1/16th corner east dug with backhoe in road, found 5"x12"x14" limestone with wood pieces and glass 18" deep. Stone was on section line and 0.2' west of midway.

6-16-1995 County Surveyor found 1/2 rod badly bent and leaning. We set up final position by measure between section corners and being .90' south of line as per stone found in 1977. This fits the Tie to 15" pine tree taken in 1977.

6-19-1995 County Surveyor referenced final position before bituminous resurface of CR #129.

9-20-1995 county highway department set 1" square pipe w/cap at surface from 1995 overlay tie out.

2-1-2011 County survey crew found 1" sq. pipe with cap in good condition.