Certificate of Location of Government Corner

ID#: 613006 **Description:** W 1/4 SEC COR 30 61 **Date Set:** 9/8/1978 **County:** Olmsted

Section: 30 **Township:** 106N **Range:** 11W **Monument Description:** Cast Iron Monument

Reference Ties:

The corner falls 1' north of north FAI-90 R/W fence and 2' east of N-S PP line
County Survey Disk in E side PP #40374 NNW 6.87'
Post w/sign 1' east
This corner is located by GPS measurement

Corner History:

10-1853 Gov't Notes John Ball, Deputy Surveyor North between sections 25 and 30. 40.00 chs. Set quarter post. Bur Oak 10 in. N87°W 39 lks. Bur Oak 12 in. S81°E 62 lks.

6-1913 D. Williams (P. 224 Book B) found a boulder in the Center of the road verified as being the ¼ corner of Sec. 25 by adjacent land owners.

1961 M.H.D. (County Highway Department corner book) found a large limestone 2' diameter with top broken off 5½' down. Found old nail 1½' down over stone. M.H.D. R/W Map for I-90 shows org. stone in place and I.P. placed.

Correction of a Corner: The correct corner is 1.9 South and 1.1 East of the M.H.D. iron (removed).

9-8-1978 County Surveyor dug at the M.H.D. iron. Found only bedrock 4½' deep beneath the iron. Dug further and found a 10"x12"x17" boulder 1' deep and just beneath the old road over pieces of broken glass. Lowered the stone and set an L-shaped iron on its NW side and a 3/4" iron on its NEside and a CIM over it. The correct corner is 1.9 south and 1.1 East of the M.H.D. location.

4-20-2009 County Surveyor found CIM down 0.4' in good condition.