Certificate of Location of Government Corner

ID#: 613105 **Description:** SW SEC COR 31 61 **Date Set:** 4/28/2009 **County:** Olmsted

Section: 31 **Township:** 106N **Range:** 11W **Monument Description:** Cast Iron Monument

Reference Ties:

The monument is down 0.6'
The corner falls 1' west of centerline of CR 136 and 3' north of centerline of E-W twp road
Punch hole in E end 30" CMP NE 59.78'
County Survey Disk in NE side PP #51082 NW 51.82'
This corner is located by GPS measurement

Corner History:

1853 Gov't Notes John Ball, Deputy Surveyor North between sections 6 and 1. 80.00 chs. Set section corner post. Dug trench and planted osage orange and apple seed. Bur Oak 10 in. N48½°E 370 lks. Bur Oak 10 in. S61½°E 195 lks.

1875 State law required monuments to be set at township corners. Thomas Hunter, County Surveyor, placed stone monuments as required although there is no survey notes documenting this particular corner

9-20-1973 County Surveyor dug in center of crossroads and found original stone monument leaning nearly flat. Found quite definite place where base of monument had originally rested. Also found boulder with wood hub near the corner location. Lowered stone monument and placed CIM on top with boulder and wood hub on north side.

6-1996 Roger Brand reports top section of CIM broken off.

7-31-1996 County Surveyor found CIM with head broken off down 12" to cross on monument.

4-27-2009 County Surveyor found CIM without head down 0.8'

4-28-2009 County survey crew removed broken CIM and found stone down 2.3' in good condition. Set new CIM over stone monument down 0.5'.

1-17-2013 County survey crew found CIM in good condition