Certificate of Location of Government Corner

ID#: 613305 **Description:** S SEC COR 32 33 61 **Date Set:** 1/4/1983 **County:** Olmsted

Section: 33 **Township:** 106N **Range:** 11W **Monument Description:** 1" square pipe with cap RLS #8952

Reference Ties:

The corner falls 2' south of centerline of CSAH 10 and in centerline of twp road north
½" rod (1/2' east of fence south) S 85.07'
1/2" rod (1/2' east of fence south) S 173.64'
This corner is located by GPS measurement

Corner History:

9-1853 Gov't Notes, John Ball, Deputy Surveyor West between sections 4 and 33. 80.00 chs. Set post for corner to sections 4,5,32,33. Black Oak 10 in. N22°E 135 lks. Burr Oak 7 in. S41°W 183 lks. Dug trench per instructions.

10-1897 William Fraser, County Surveyor, (Book A. Page 612, No. 556) "Found the remains of old stake in center of road where Mr. S.M. Carpenter said the old stake use to stand which was 48 links North of the end tree of a row of trees on the South side of road running West. Drove new stake with two stones by its side in place of old stake." He used the corner to set
the N. ¼ Cor. 4, a temporary stake, midway (39.94½ chs.) and on line to the N. Sec. Cor. 3-4, and to Set ¼ Cor. 4-5, a temporary stake, at "one third the distance (39.97 chs.) from C (N. Sec. Cor. 4-5) to West Quarter post of Section No. 9."

1935 county highway department (C.H.D. Book 75, Page 7) "Found old wooden stake about 1.5 ft. below surface with 2"x8"x18" limestone on North side of stake. Used center of stone."

8-1935 county highway department (C.H.D. Book 83, Page 2) "Found old wooden stake 1.5 below surface with 2"x8"x18" limestone N. side. Set stake on top of center of stone.

6-17-1976 County Surveyor dug and found a hub over 2 limestones (down 3½') over a stake running down 12". Drove a ½"x20" rod in the stake hole and set a ½" rod at the road surface. The corner is in the centerline of the road North and 1' East of the line of the fence running South.

8-8-1977 County Surveyor took references before road grading. Set a ½" rod (1' East of the fence South), South 85.07 and on line to a ½"x2' rod (½' East of fence South) South 173.64.

5-19-1982 County Surveyor the corner is now in deep fill in newly graded C.R. 10. The County Surveyor set a 1" sq. by 13" long pipe as corner from references taken 8-8-1977.

1-4-1983 County Surveyor found that the Southerly reference iron placed 8-8-1977 had been bent over by tractor. Set a 1" square pipe with cap in new concrete on C.R. 10 as corner at 85.07 North of the ½" rod set 85.07' South in 1977 and 5273.16' West of S. Sec. Cor. 33-34 as measured and platted in 1978 (See Olmsted County Highway Right of Way Plat No. 9)

7-23-2003 County Surveyor found 1" square pipe w/cap at surface in good condition.